

STATEMENTS OF SIGNIFICANCE

Donald Luxton & Associates

Sept 19.

Name Of Historic Place	Connaught School m#
Address & Municipality	
Site Info (drawings, references, history)	1912.
Site Features (location, siting & views)	
Integrity (additions, condition of elements)	

STATEMENTS OF SIGNIFICANCE

Donald Luxton & Associates

1913 - Cornerstone 1912

Full city block

banked brick on west side + windows

CDE's	
- form, scale and massing (plan, massing, roof, dormers)	rectangular plan w/ projecting ends + corner towers new shingle siding projecting central entry w/ full height basement concrete foundation
- construction material (structure, walls, material + location)	red brick - recessed grey mortar - Sandstone quoins - combed
- style details (trim, decorative elements)	quoins - Shingled cupola w/ louvers - curved + notched exposed rafters pilasters delineating window bays dark clay tile inlay at tower peaks
- verandahs and porches dormer	- central entrance corner towers - capped - upper lanterns Δ brackets - massive 1/2 timbring w/ pebble barge board. stucco
- other details (chimneys, flagpoles)	- interior red brick chimney w/ sandstone cap
- windows (assembly, type, material, decorative element)	banked windows - regular decorative window hoods
- doors	projecting bay full height bay w/ windows on east facade w/ 1/2 timbring + stucco + west. notched barge boards
- interior features	rear elevation boys + girls entryways recessed w/ transoms light.
- newel posts - interior transoms lights	side

- Integrity: cornerstone deteriorating
doors replaced
some mortar missing + cracked.
- missing