


STATEMENTS OF SIGNIFICANCE

Donald Luxton & Associates

Name Of Historic Place	St Barnabas Church + Hall
Address & Municipality	(1912-13) (1960)
Site Info (drawings, references, history)	- Set back Jeague - ST. Calgary Sid bell from - 
Site Features (location, siting & views)	- sloped grass lot - set back. - mature tree line. - cast concrete block retaining wall - capped
Integrity (additions, condition of elements)	changed windows at top parish Hall - 1960 - Brick sills + lintels + pointed arch windows - parking - cracked spalling nesting. - smoothed over stucco. - windows - 1970s

STATEMENTS OF SIGNIFICANCE

Donald Luxton & Associates

CDE's	
- form, scale and massing (plan, massing, roof, dormers)	side gabled with front gabled projection often centre tower with p.crenelated 1 st w/ full basement 3 dormers (same in Back)
- construction material (structure, walls, material + location)	brick - common bond - white mortar w/ pebbles. sandstone - detailing - paved concrete
- style details (trim, decorative elements)	8 tower - crenelated tower - brick buttresses w/ sandstone caps - brick lintels Sandstone banding. - exposed/notched rafters - fascia. Combed sandstone
- verandahs and porches	dormers - 1/2 timbering - decorative rafters - Whale bone bargeboards. 2- entrance on east side - sand doorway.
- other details (chimneys, flagpoles)	- Sandstone cross in tower + corner stone.
- windows (assembly, type, material, decorative element)	windows with tracery. - door - inset with pointed arch + leaded coloured glass - door in tower with strapping - inset in pointed arch doorway. - stained glass - w/ rmt. - leaded.
- doors	Leasements in basement. 1/1 in basement.
- interior features	changed w/ exterior stairs - aluminum gas lights on columns wall radiator 1912 pews floods massive arches oak pews cassava organ

Robert
L. McLaughlin
Toronto 1953

Macosha
- 50's
in brick
wood
Church
Hall
below wood floor

1970s
wood floor

plaster walls
trim
radiators
columns - scroll cut detail

